




Switch Boxes



Features...

- ★ "Exact Fit" means no splicing, no special adapters, and no modifications required.
- ★ Fast and easy plug and play installation for a more reliable and labor saving repair.
- ★ All are manufactured in a state-of-the-art facility using the latest technology in components.
- ★ Our designs are installed and field tested by marine professionals to assure proper performance and quality.
- ★ Supported by our easy-to-read application charts, found only in our award-winning catalog.
- ★ Sierra is the only aftermarket company to back electronic ignition parts with a comprehensive warranty that covers labor.

 <p>18-5775 AP# 1852 SWITCH BOX Replaces: 332-7778A6, 332-7778A9,A12</p>	 <p>18-5776 AP# 13403 SWITCH BOX Replaces: 339-7452A3</p>	 <p>18-5777 AP# 13404 SWITCH BOX Replaces: 339-7452A15, A19</p>	 <p>18-5778 AP# 13405 SWITCH BOX Replaces: 339-7452A14, A21</p>
 <p>18-5779 AP# 13406 SWITCH BOX Replaces: 332-2986A21, 332-2986A22, 332-2986A25, 332-2986A27</p>	 <p>18-5786 SWITCH BOX ASSEMBLY Replaces: 332-4911A2 For: 20 HP</p>	 <p>18-5787 SWITCH BOX ASSEMBLY Replaces: 332-4911A8 For: 40 HP</p>	 <p>18-5788 SWITCH BOX ASSEMBLY Replaces: 339-6222A8 For: 4 HP</p>
 <p>18-5789 SWITCH BOX ASSEMBLY Replaces: 339-6222A10 For: 7.5/9.8 HP</p>	 <p>18-5790 SWITCH BOX ASSEMBLY Replaces: 18495A26 For: 75-90 HP</p>	 <p>18-5791 SWITCH BOX ASSEMBLY Replaces: 19052A8 For: 50-60 HP</p>	 <p>18-5792 SWITCH BOX ASSEMBLY Replaces: 16061T For: 4/5 HP</p>
 <p>18-5793 SWITCH BOX ASSEMBLY Replaces: 823034T For: 2.5/3.3 HP</p>	 <p>18-5881 AP# 3107 SWITCH BOX Replaces: 332-5772A7</p>	 <p>18-1151 AP# 13031 ROTOR SHAFT BEARING Replaces: 30-20066 SKF France R822T</p>	 <p>18-1152 AP# 13032 ROTOR SHAFT BEARING Replaces: 30-26379 SKF France 6002-2 RSI/HT</p>

APPLICATIONS ON NEXT PAGE

OUTBOARD