



18-5009
AP# 13343
TUNE-UP KIT
— CONTAINS —

Sierra #	AP #	O.E.#	Description
18-5161	732	38850127	Contact Set
18-5241	13385	38850115	Condenser

For 10 H.P. 1958



18-5153
AP# 13360
CONTACT SET
Replaces: 75101A,
1340135, 36550135



18-5161
AP# 13362
CONTACT SET
Replaces: 38850127



18-5162
AP# 13363
CONTACT SET
Replaces: 73739



18-5236
CONDENSER
Replaces: 76067, 36850115



18-5241
AP# 13385
CONDENSER
Replaces: 38850115

HP	Years	Sierra Contact Set	Sierra Condenser
3.6	1953-57	18-5153	—
3.6	1958-59	18-5161 ①	—
5	1958-59	18-5161 ① ② ④	—
6	1960-62	18-5153 ②	—
7.5	1952-87	18-5153 ②	—
7.5	1958	18-5153 ② ③	—
7.5	1958	18-5161 ① ②	—
7.5	1960	18-5153 ②	—
7.5	1961-68	18-5153 ②	—
10	1958	18-5161 ②	18-5241 ②
22	1958	18-5162 ②	18-5236 ②
25	1959	18-5153 ② ③	—
25	1959-60	18-5162 ① ②	18-5236 ① ②
28	1961-68	18-5162 ②	18-5236 ②
30 to 33	1955-56	18-5153 ②	—
40	1957-59	18-5153 ② ③	—
40	1958-60	18-5162 ① ②	18-5236 ① ②
43.7	1961-62	18-5162 ②	18-5236 ②
45	1963-67	18-5162 ②	18-5236 ②
50	1964	18-5162 ②	18-5236 ②

① WICO Magneto Only ② Two Required ③ REPCO Magneto Only ④ Models without "M" S/N Only

OUTBOARD