

YAMAHA

Drive System



 <p>18-6034 ①18-6034A AP# 4050 TRIM TAB 90-200 H.P. Replaces: 6K1-45371-00-00</p>	 <p>18-6035 AP# 4049 TRIM TAB 150-200 H.P. Replaces: 6J9-45371-01-00</p>	 <p>18-6096 ①18-6096A TRIM TAB Replaces: 664-45371-01 For: 20-50 HP</p>	 <p>18-6097 ①18-6097A AP# 4077 TRIM TAB Replaces: 6E5-45371-01 For: 115-200HP</p>	 <p>18-6036 ANODE 40-90 H.P. Replaces: 688-45251-01-00</p>	 <p>18-6070 ①18-6070A AP# 4052 ANODE Replaces: 688-45371-02-00</p>
 <p>18-6090 ①18-6090A ANODE Replaces: 6G5-45251-01-00</p>	 <p>18-6091 AP# 4076 ANODE Replaces: 6H1-45251-02-00 For: 40-90HP</p>	 <p>18-6111* MAGNESIUM ANODE Replaces: 688-45371-02 For: 60-90HP</p>	 <p>18-6112* MAGNESIUM ANODE Replaces: 6J9-45371-01 For: 150-200 HP</p>	 <p>18-6113* MAGNESIUM ANODE Replaces: 664-45371-01 For: 20-50 HP</p>	

① New Product - Aluminum * FRESH WATER USE ONLY

 <p>18-2247 PROPELLER SHAFT Replaces: 679-45611-01-00 For: 40-50HP</p>	 <p>18-2385 PROPELLER SHAFT Replaces: 6E5-45611-01-00 For: 115/130HP</p>	 <p>18-2388 PROPELLER SHAFT Replaces: 688-45611-00-00 For: F40 (1999) F50(1999-00) C60/C70/C90/90 (2000-01) C75 (1994) C85 (1991-94)</p>
--	---	--

Model No.	Year	Sierra No.	Model No.	Year	Sierra No.
40	1984-86, 89-90, 92-94	118-2247	C90	2000-2001	118-2388
C40	1991-93, 95-97	118-2247	115	1984-2000, 2002-2003	118-2385
CV40	1990	118-2247	C115	1991, 1993-2000	118-2385
50	1986-1994	118-2247	F115	2000-2003	118-2385
P50	1991-1994	118-2247	LF115	2000-2003	118-2385
PRO50	1987-1990	118-2247	S115	1996-1999	118-2385
T50	1999-2000	118-2388	130	1984-2000, 2002-2003	118-2385
C60	2000-2001	118-2388	L130	1994-2000	118-2385
C70	2000-2001	118-2388	S130	1996-1999	118-2385
C75	1994	118-2388	150	1985, 1997	118-2385
E75	2000	118-2388	175	1985	118-2385
C85	1991-1994	118-2388	200	1984-1985	118-2385
CV85	1990	118-2388	V6 Special	1985-1986	118-2385

OUTBOARD