



- 1 High strength synthetic cords resist shockload failure. Their low stretch properties assure uniform performance over the life of the belt.
- 2 The compression section is a special rubber compound that assures smooth and even transfer of load forces to the cords.
- 3 Cogs are molded to precise engineering tolerances to improve flexibility and maintain cord support. Cog geometry provides a large area for air circulation to keep the belt cool and prevent damaging heat build up in the cushion section.
- 4 Rubber edges maintain positive, no-slip contact with pulley grooves for reliable energy transfer.

V - BELT APPLICATION

Sierra No.	OE No.	Application
18-15106	YSC-13260-60-0C	2 HP 1986-88
18-15107	YSC-13260-70-0C	2 HP 1989-02
18-15108	YSC-22260-10-0C	4 HP (1984-99) / F4 (1999-02) / 5HP (1984-02)
18-15109	YSC-22260-00-0C	6 HP (1986-96) 8 HP (1984-96)
18-15110	YSC-10260-10-0C	20HP (1997-97) 25HP (1988-02) 2cyl model
18-15111	YSC-10260-00-0C	6 HP 1997-00



18-5280
AP# 3072
COMPLETE
TUNE-UP KIT
For: In-line 4



18-5278
AP# 3073
COMPLETE
TUNE-UP KIT
For: V-6











High Performance Marine Spark Plug Wire Sets Inboard & Stern Drive



- ★ NEW Spiral wound stainless steel & Kevlar™ core delivers the **hottest** spark
- ★ Pure silicone boot & jacket protects up to **500 F** (260 C)
- ★ 8mm diameter for more efficient spark delivery
- ★ Stainless steel snaplock terminals resist performance robbing corrosion
- ★ Protects electronics from the frustrating effects of RFI & EMI interference (Meets SAE J1191 specifications)

Model	Ignition Type	Cyl.	Sierra #	AP #
4.3L	Delco EST	V-6	18-8810	3034
5.0L/5.7L	Delco EST	V-8	—	3039
7.4l	Delco EST	V-8	—	3039

YAMAHA STERNDRIVE GASKETS

 <p>18-0164 AP# 345 THERMOSTAT HOUSING Replaces: YSC-13080-00-0C, GM 3789161</p>	 <p>18-0876 AP# 531 WATER PUMP MOUNTING Replaces: YSG-10108-43-8G</p>	 <p>18-0889 AP# 348 FUEL PUMP MOUNTING Replaces: YSG-10114-14-1G</p>	 <p>18-0891 AP# 352 PUMP MOUNTING Replaces: YSG-37545-87-G0</p>	 <p>18-0874 AP# 350 DISTRIBUTOR Replaces: YSG-10108-11-5G</p>
 <p>18-2909 AP# 101 EXHAUST MANIFOLD MOUNTING GASKET Replaces: YSC-12190-00-AC For: 262 CID (4.3L)</p>	 <p>18-0903 AP# 536 WATER PUMP Replaces: YSG-38600-39-G0</p>	 <p>18-0887 AP# 355 TIMING COVER Replaces: YSG-14096-15-6G</p>	 <p>18-0905 AP# 356 OIL PAN DRAIN PLUG Replaces: YSG-14090-90-8G</p>	 <p>18-4698 AP# 2097 DRAIN OR FILL WASHER Replaces: YSG-14090-90-8G</p>