



OIL FILTERS

ACCESSORIES

Make—Model—Year	Sierra Oil Filter	Make—Model—Year	Sierra Oil Filter
Interceptor IV4-80, OV4-80, OV6-100 (Taunus), 80, 85, 100, 110, 120, (1960-on), 140, 190, 200, 210, Interceptor 160, Interceptor 165 SPIN ON LUBE	18-7878	Mercury/Mariner (Cont.) OG760300 & Up, 75/90HP s/n OG960500 & Up Replaces: Mercury 35-822626Q 2	18-7914
Johnson Surfer (w/V8-327) SPIN ON LUBE Replaces: OMC 173233 Replaces: OMC 173232 Replaces: 434839	18-7824 18-7876 18-7824 18-7916	Mohawk V8-302, V8-351 SPIN ON LUBE	18-7875
Lehman Models (w/Ford 242), (w/Ford 254), (w/Ford 363), (w/Ford 380), (Lehman 2N50) SPIN ON LUBE	18-7875	Nissan All 4 stroke engines Replaces: 3RO-07615-0	18-7911
Marine Power, Inc. 3.0L, 350 (5.7L) 454 (7.4L) ENPACK Replaces: Marine Power 0905-000-0	18-7824 18-7876 18-7824	OMC 170 (1974), 175 (1975-77) 190 (1974-77), 235 (1975-77) 240 (1978), 2.3L (1987), 7.5L (1987) SPIN ON LUBE Replaces: OMC 173231	18-7875
Mercuriser 60, 80 SPIN ON LUBE	18-7878	205, 229 (Chevrolet V6), 175 3.8L (1981), 4.3L (1986) SPIN ON LUBE Replaces: OMC 173834	18-7879
175, 185, 205 Replaces: Mercuriser 41815, 35-802884Q	18-7879	M-100, M-200 (1961-on) SPIN ON LUBE	18-7878
88 (188), 215, 233, 235, 250, 255 225, 225-S SPIN ON LUBE Replaces: Mercuriser 60565, 35-802886Q	18-7875	210 (1970), 100 (1973), 165 (1973-76), 2.5L (1982-86), 3.0L (1982-87), 120, 140 (1973-81) SPIN ON LUBE Replaces: OMC 173232	18-7824
160, 470 (170), 485 (185), 488 (188) 190 SPIN ON LUBE Replaces: Mercuriser 54111 Replaces: Mercuriser 14957 190, 898 (198), 225, 270, 390 REMOTE MOUNT SPIN ON LUBE Replaces: Mercuriser 14957 Replaces: Mercuriser 52731, 35-16595T1 Replaces: Mercuriser 54111, 35-802885Q	18-7824 18-7824 18-7876 18-7824	165 (1972), 185 (1978-80), 200 (1979-81,) 210 (1971-72) 225 (1973-76, 78), 230 (1975-76, 1978-81), 245 (1973-75), 250 (1970-72), 260 (1975-76, 1979-81), 290 (1974-75), 305 (1977-80, 82), 350 (1977-80, 82) 454 (1977-82) 5.0L (1982-present) 5.7L (1982-present) SPIN ON LUBE Replaces: OMC 173233 Replaces: OMC 173232	18-7824 18-7876 18-7824
120, 140, 150, 160, 165, 170, 180, 200, 230, 250, 300, 320 EFI, 325, 340, 350, 370, 350 MAG, 454 MAG, 400, 525, 2.5L, 3.0L, 5.0L, 5.7L, 7.4L, 228, 260, 280, 255, 330 SPIN ON LUBE Replaces: Mercuriser 14957 Replaces: Mercuriser 52731 Replaces: Mercuriser 54111	18-7824 18-7876 18-7824	OMC / Bombardier (99-02) 40/50 4 stroke (00,01) 25/30 4 stroke (01-03) 70 4 stroke (02,03) 60 4 stroke Replaces: OMC/Bombardier	18-7915
7.3L/270 Diesel 7.3L Bravo Diesel Replaces: Mercuriser 35-805809, 35-805809T	18-7871	Onan JA, JB, JB (Ind. eng.), JC gen., JC (Ind. eng.), MJA, MJB, MJC, J-30, J-60, J-120, RDJF, RJC, DJA, DJB, DJC, MDJA, MDJB, MDJC, RDJC, DJ-30, DJ-60, DJ-120, JD-130 MDJ-30, MDJ-130, 6MDJB-37, 15MDJC-3R, 3.0 DJA, DJE, 6.0 DJB, MDJE, MDJF, NH, 7.5 MDJE, 15MDJF, 15 MDJ-3R, 705 MDJE-3R, 150 MDJF, DJB Gen. (Standard) SPIN ON LUBE Replaces: Onan 122-0185	18-7878
Mercuriser Diesel 0219 Turbo Diesel Blue Water (Bravo Series) D254 Turbo Diesel Blue Water (Bravo Series) SPIN ON LUBE Replaces: Mercuriser FIAAMFT4805	—	EF SPIN ON LUBE	18-7875
Mercury/Mariner 9.9 4 Stroke S/N H000058-H017099 Replaces: Mercury 825467A1, 825467T1 4 Stroke O/B's, 9.9/15 & 8/15 Bodensee OG760300 & Up Replaces: Mercury 35-822626Q 1 4 Stroke O/B's, 25/30/40/45/50HP s/n	18-7901 18-7913	Onan (Generator Sets) 3.0 Aux. (w/MDJA diesel eng.) SPIN ON LUBE Replaces: Onan 122-0185	18-7878
		Palmer AD-21 SPIN ON LUBE	18-7878
		P302, P351, P460, PA190, PA220, PA255 SPIN ON LUBE	18-7875