


| PISTON APPLICATION (Cont.) | | | | | | | |
|----------------------------|------------------------------|---------|---------|---------|---------|---------|-------|
| HP/Model | Years | PISTON | | | RINGS | | |
| | | Std. | .25mm | .50mm | Std. | .25mm | .50mm |
| P40 | 1998 | — | — | 18-4143 | 18-3960 | 18-3961 | — |
| E48 | 1997 | 18-4097 | 18-4098 | 18-4099 | 18-3969 | 18-3970 | — |
| 50 | 1986-88 | 18-4141 | 18-4142 | 18-4143 | 18-3960 | 18-3961 | — |
| 50 | 1996-97, 1999, 2000, 2002-03 | 18-4141 | 18-4142 | 18-4143 | 18-3960 | 18-3961 | — |
| C50 | 1998-99, 2001 | — | 18-4142 | 18-4143 | 18-3960 | 18-3961 | — |
| P50 | 1996 | — | 18-4142 | 18-4143 | 18-3960 | 18-3961 | — |
| P50 | 1987-88 | 18-4141 | 18-4142 | 18-4143 | 18-3960 | 18-3961 | — |
| 55 | 1993-95 | 18-4097 | — | 18-4099 | 18-3969 | 18-3970 | — |
| 60 | 1984-98 | 18-4091 | — | 18-4093 | 18-3963 | — | — |
| 60 | 2002-03 | 18-4091 | — | 18-4093 | 18-3963 | — | — |
| C60 | 1996-01 | 18-4091 | — | 18-4093 | 18-3963 | — | — |
| E60 MLH,T,U,V | 1995-97 | 18-4094 | — | 18-4096 | 18-3963 | — | — |
| P60 | 1991-99 | 18-4091 | — | 18-4093 | 18-3963 | — | — |
| 70 | 1984-98 | 18-4091 | — | 18-4093 | 18-3963 | — | — |
| 70 | 1999-03 | 18-4091 | — | 18-4093 | 18-3963 | — | — |
| C70 | 2000-01 | 18-4091 | — | 18-4093 | 18-3963 | — | — |
| 75 | 1994-98 | 18-4097 | 18-4098 | 18-4099 | 18-3969 | — | — |
| C75 | 1996 | 18-4097 | 18-4098 | 18-4099 | 18-3969 | — | — |
| C75 | 1998-99 | 18-4097 | 18-4098 | 18-4099 | 18-3969 | — | — |
| E75 | 1996 | 18-4097 | 18-4098 | 18-4099 | 18-3969 | — | — |
| E75 | 1997 | 18-4097 | 18-4098 | 18-4099 | 18-3969 | — | — |
| P75 | 1996-99 | 18-4097 | 18-4098 | 18-4099 | 18-3969 | — | — |
| C80 | 1997 | 18-4097 | 18-4098 | 18-4099 | 18-3969 | — | — |
| C85 | 1992-96 | 18-4097 | 18-4098 | 18-4099 | 18-3969 | — | — |
| 90 | 1994-99 | 18-4097 | 18-4098 | 18-4099 | 18-3969 | — | — |
| C90 | 1997-01 | 18-4097 | 18-4098 | 18-4099 | 18-3969 | — | — |

| V4 & V-6 Engines | Years | Port Std. | Stbd. Std. | Port .25mm | Stbd. .25mm | Port .50mm | Stbd. .50mm | Std. | |
|--------------------------------|-------|-----------|------------|------------|-------------|------------|-------------|---------|---------|
| 115 w/22mm wrist pin | V-4 | 1984-86 | 18-4128 | 18-4129 | 18-4130 | 18-4131 | 18-4132 | 18-4133 | 18-3934 |
| 115 w/22mm wrist pin | V-4 | 1987-92 | 18-4128 | 18-4129 | 18-4130 | 18-4131 | 18-4132 | 18-4133 | 18-3934 |
| 115 w/23mm wrist pin | V-4 | 1993-03 | 18-4080 | 18-4081 | 18-4082 | 18-4083 | 18-4084 | 18-4085 | 18-3934 |
| 130 w/22mm wrist pin | V-4 | 1984-92 | 18-4128 | 18-4129 | 18-4130 | 18-4131 | 18-4132 | 18-4133 | 18-3934 |
| 130 w/23mm wrist pin | V-4 | 1993-03 | 18-4080 | 18-4081 | 18-4082 | 18-4083 | 18-4084 | 18-4085 | 18-3934 |
| 150, 175 w/22mm wrist pin | V-6 | 1984-92 | 18-4128 | 18-4129 | 18-4130 | 18-4131 | 18-4132 | 18-4133 | 18-3934 |
| 150, 175 w/23mm wrist pin | V-6 | 1993-99 | 18-4080 | 18-4081 | 18-4082 | 18-4083 | 18-4084 | 18-4085 | 18-3934 |
| 200, 225 w/22mm wrist pin | V-6 | 1984-92 | 18-4128 | 18-4129 | 18-4130 | 18-4131 | 18-4132 | 18-4133 | 18-3934 |
| 200, 225 w/22mm wrist pin | V-6 | 1993-99 | 18-4080 | 18-4081 | 18-4082 | 18-4083 | 18-4084 | 18-4085 | 18-3934 |
| V6 SPECIAL J,K,L,N,XN (6G7)V-6 | | 1984-86 | 18-4128 | 18-4129 | 18-4130 | 18-4131 | 18-4132 | 18-4133 | 18-3934 |

| | | |
|---|--|---|
|  <p>18-4157 CONNECTING ROD Replaces: 6R5-11650-10-00 For: V6 150/175/200</p> |  <p>18-4158 CONNECTING ROD Replaces: 6E5-11650-01-00 For: V4 115/140</p> |  <p>18-4077 ROD BEARING Replaces: 93310-730V8 For: 45, 55, 90 HP -3 Cyl.</p> |
|  <p>18-4078 ROD BEARING Replaces: 93310-836V2 For: V4 & V6 (1990 motors)</p> |  <p>18-2773 BEARING CARRIER Replaces: 663-45331-00-94 For: E48 (1995, 1997-00) / C55 (1991-95)</p> |  <p>18-2782 BEARING CARRIER Replaces: 688-45331-00-94 For: F40 (1999) F50/T50 (1996-00) 60 (2002-03) C60 (1998-01) E60 (1995-99) P60 (1991-99) 70 (1984-03) C70 (2000-01) C75 (1994-96 / 1998-99) E75 (1995-00) P75 (1996-99) C80 (1997) C85 (1991-96)</p> |

Features...

- ★ Manufactured to meet or exceed OEM specifications.
- ★ Made by a leading OEM supplier.
- ★ Field-tested and approved.



| Sierra # | AP # | Replaces: |
|----------------|------------------|--|
| 18-7824 | 6003/6006 | For: All V-8 5.0L, 5.7L - Spin On Lube |
| 18-7876 | 6005 | For: All V-8 5.0L, 5.7L - Spin On Lube |
| 18-7875 | 6007 | For: All V-6 4.3L |
| 18-7901 | — | 6G8-13440-00-00 For: F&T 9.9 (1990-99) |
| 18-7902 | 13528 | 3FV-13440-00-00 For: F15 (1998-99), F40 (1999), F25 (1998-99), F&T50 (1995-98), F80 (1999), F100 (1999) |
| 18-7906 | F200/F225 | 69J-13440-00-00 |
| 18-7911 | — | 5GH-13440-00-00 For: F15 (2000-03), F&T 25 (2000-03), F40 (2001-03), F&T 50 (2000-03), F60, F80, F100 (2000-03), F115 |

OUTBOARD