














 <p>18-5311 AP# 2810 CONTACT SET</p>	 <p>18-5314 AP# 2861 CONTACT SET Replaces: 20117</p>	 <p>18-5318 AP# 855 CONTACT SET Replaces: 3000124</p>	
 <p>18-5338 AP# 862 CONDENSER Replaces: 12530</p>	 <p>18-5344 AP# 2852 CONDENSER Replaces: 12526</p>	 <p>18-5345 AP# 2807 CONDENSER Replaces: 41057, 705787</p>	
 <p>18-5347 CONDENSER</p>	 <p>18-5403 ROTOR Replaces: 41089, 41074</p>	 <p>18-5404-1 AP# 2863 ROTOR Replaces: 20223</p>	 <p>18-5405 AP# 3064 ROTOR Replaces: 38071 Use with 18-5354/AP# 3062 Distributor Cap Fits new GM style "Module in Cap" distributors - V-8 application</p>
 <p>18-5406 AP# 3063 ROTOR Use with 18-5361 Distributor Cap</p>	 <p>18-5407 AP# 866 ROTOR Replaces: 41059</p>	 <p>18-5408 AP# 3065 ROTOR Use with 18-5362/AP# 3061 Distributor Cap Fits new GM Style "Module in Cap" Distributors V6 Applications</p>	
 <p>18-5409 AP# 530 ROTOR</p>	 <p>18-5411 AP# 869 ROTOR Replaces: 12531,1003318</p>	 <p>18-5418 AP# 2811 ROTOR</p>	

INBOARD

APPLICATION BEGINS ON PAGE 434