






















<p>PKG. OF 2</p>  <p><b>18-0388</b> AP# 396 <b>HYDRAULIC CONNECTOR</b> Replaces: 27-98823-1</p>	<p>PKG. OF 2</p>  <p><b>18-0318</b> AP# 2394 <b>WASHER</b> Replaces: 12-815472</p>	<p>PKG. OF 5</p>  <p><b>18-0203</b> <b>BELL HOUSING STUD WASHER</b> Replaces: 12-35935 All Mercruiser Stern drives 1963-1998</p>	 <p><b>18-0905</b> AP# 356 <b>OIL PAN DRAIN PLUG</b> Replaces: 27-49955</p>																																
<p>PKG OF 2</p>  <p><b>18-2944</b> AP# 221 <b>OIL PASSAGE SEAL (Quad Ring)</b> Replaces: 26-45577</p>	<p>PKG OF 2</p>  <p><b>18-2945</b> AP# 2108 <b>GEAR HOUSING DRAIN SCREW</b> Replaces: 12-20260, 12-19183, 12-191832</p>	<p>PKG OF 5</p>  <p><b>18-2948</b> AP# 1587 <b>GEAR HOUSING PLASTIC FLUSH SCREW</b> Replaces: 12-49221-1, 12-49221</p>	 <p><b>18-2722</b> AP# 1954 <b>RUBBER PLUG</b> Replaces: 19-59504</p>																																
 <p><b>18-4267</b> <b>SHIFT SHAFT WASHER</b> Replaces: 12-29395</p>	 <p><b>18-2349</b> <b>SHIFT SHAFT SLEEVE</b> Replaces: 23-67370 For: Gen II (S/N D469859-F679999)</p>	 <p><b>18-0681</b> AP# 338 <b>WASHER</b> Replaces: 12-32834</p>	 <p><b>18-2316</b> AP# 131 <b>WASHER</b> Replaces: 12-77674 For: Gen II (Lower) S/N D469859 &amp; up</p>																																
 <p><b>18-4269</b> <b>WASHER</b> Replaces: 12-29245</p>	<p>PKG OF 2</p>  <p><b>18-4270</b> <b>WASHER</b> Replaces: 12-36001</p>	 <p><b>18-4272</b> AP# 13274 <b>WELCH PLUG</b> Replaces: 19-32652</p>	 <p><b>18-4273</b> AP# 13275 <b>WELCH PLUG</b> Replaces: 19-42682</p>																																
<p><b>FASTENERS</b></p> <table border="1"> <thead> <tr> <th>Sierra #</th> <th>AP #</th> <th>Description</th> <th>O.E. #</th> </tr> </thead> <tbody> <tr> <td>18-3233</td> <td>5179</td> <td>Manifold to Elbow Stud 3/8" - 24 3/8" - 16 x 5 1/4"</td> <td>16-49545</td> </tr> <tr> <td>—</td> <td>5161</td> <td>Manifold Mounting Screw 3/8" - 16 x 4 5/8"</td> <td>10-53728</td> </tr> </tbody> </table>		Sierra #	AP #	Description	O.E. #	18-3233	5179	Manifold to Elbow Stud 3/8" - 24 3/8" - 16 x 5 1/4"	16-49545	—	5161	Manifold Mounting Screw 3/8" - 16 x 4 5/8"	10-53728	<p><b>SCREWS</b></p> <table border="1"> <thead> <tr> <th>Sierra #</th> <th>AP #</th> <th>Description</th> <th>O.E. #</th> </tr> </thead> <tbody> <tr> <td>18-2361</td> <td>5207</td> <td>Lower Unit Mounting Screw</td> <td>10-30206</td> </tr> <tr> <td>18-3197</td> <td>2679</td> <td>Water Pick-Up Insert Screw</td> <td>10-76156</td> </tr> <tr> <td>18-3230</td> <td>—</td> <td>Gear Housing To Drive Shaft Housing Screw</td> <td>10-816601</td> </tr> <tr> <td>18-3231</td> <td>—</td> <td>Upper Drive Shaft Top Cover Screw</td> <td>10-98794</td> </tr> </tbody> </table>		Sierra #	AP #	Description	O.E. #	18-2361	5207	Lower Unit Mounting Screw	10-30206	18-3197	2679	Water Pick-Up Insert Screw	10-76156	18-3230	—	Gear Housing To Drive Shaft Housing Screw	10-816601	18-3231	—	Upper Drive Shaft Top Cover Screw	10-98794
Sierra #	AP #	Description	O.E. #																																
18-3233	5179	Manifold to Elbow Stud 3/8" - 24 3/8" - 16 x 5 1/4"	16-49545																																
—	5161	Manifold Mounting Screw 3/8" - 16 x 4 5/8"	10-53728																																
Sierra #	AP #	Description	O.E. #																																
18-2361	5207	Lower Unit Mounting Screw	10-30206																																
18-3197	2679	Water Pick-Up Insert Screw	10-76156																																
18-3230	—	Gear Housing To Drive Shaft Housing Screw	10-816601																																
18-3231	—	Upper Drive Shaft Top Cover Screw	10-98794																																
<p>PKG OF 5</p>  <p><b>18-2362</b> AP# 5164 <b>GEAR HOUSING TO DRIVE SHAFT HOUSING NUT</b> Replaces: 11-13439-1, 11-859116 For: MR/Alpha</p>	<p>PKG OF 5</p>  <p><b>18-2344</b> AP# 13083 <b>WATER PICK-UP INSERT NUT</b> Replaces: 11-45812 Use with 18-3198</p>	 <p><b>18-3236</b> <b>HOUSING ALIGNMENT BUSHING</b> Replaces: 23-32632 For: #1R/MR/Alpha</p>	<p>PKG OF 5</p>  <p><b>18-2340</b> AP# 132 <b>SHIFT SHAFT RUBBER WASHER</b> Replaces: 12-31266 For: #1R/MR (1/16" Thick)</p>	<p>PKG OF 2</p>  <p><b>18-2343</b> AP# 13082 <b>PINION NUT WASHER</b> Replaces: 12-92721 For: MR/Alpha/Gen II</p>																															

SEE PAGES 101-102 FOR OUR COMPLETE LINE OF GASKET SEALANT