

# OIL FILTERS



ACCESSORIES

Oil Filter Application			
Make—Model—Year	Sierra Oil Filter	Make—Model—Year	Sierra Oil Filter
<b>Albin</b> AD-21 SPIN ON LUBE Replaces: ALBIN 3875827	<b>18-7878</b>	<b>Detroit Diesel (cont.)</b> 12V-149 (1788), 16V-71 (1136), 16V-71T (1136), 16V-92 (1472), 16V-92T (1472), 16V-149 (2384) Series Replaces: Detroit Diesel 25010495	<b>18-7899</b>
<b>B &amp; W Lathrop</b> 130155 SPIN ON LUBE	<b>18-7875</b>	<b>Evinrude</b> Explorer (w/V8-350), Rogue (w/V8-307), w/V8-327) SPIN ON LUBE Replaces: OMC 173233 Replaces: OMC 173233 Replaces: OMC 173232	<b>18-7824</b> <b>18-7824</b> <b>18-7824</b>
<b>Caterpillar</b> 3304, 3306, D330 Replaces: Caterpillar 1R-0658	<b>18-7880</b>	<b>Flagship</b> 150FA, 220FF, 250FA, 400FA, 425FAJ, 650FAJ, 950FAJ SPIN ON LUBE	<b>18-7824</b> <b>18-7824</b> <b>18-7824</b>
<b>Chris-Craft</b> 307G, 305K,307K SPIN ON LUBE Replaces: Chris Craft 16.81-08746	<b>18-7824</b>	292, 300, 307, 327, 350, 482 SPIN ON LUBE	<b>18-7876</b> <b>18-7824</b>
<b>Chrysler</b> (Chrysler-Volvo) 100, 110, 120, 130, 165, 170 SPIN ON LUBE	<b>18-7878</b>	<b>Ford</b> CSG850M WSG858M,LSG875M,SSD-655, -655M, -655MT, (5.5 Liter), 140(2.3L) FOUR, 170, 200 Six, 240 Six, 300 Six, 302 (5.0L),351 (5.8L), 460 (7.5L),2711E, 2712E, 2713E, 2714E, 2715E (diesel) SPIN ON LUBE	<b>18-7875</b>
125, 150, 155, 175, Fury 190, 195, 200, 210,225, 235, 250, 260, 280, 300, 330, 335, 375, 525, CM6-55, CMC-55NA, M-170A, M-225A, M-225D, M-273A, M-273B, M-273BO/D, LM-318, LM-318A, LM-318B, M-318B, M-318C, M-383B, M-413B, M-413D, M-413E, M-440B, M-440D, Model 340,M-80, M-81, Super Crown 145, 150, Imperial 290, 325, Jet II, Jet III, Jet IV, Super Bee, Super Bee II,Super Bee III, V-8 Engines 1962-on SPIN ON LUBE Replaces: Chrysler 1851658	<b>18-7875</b>	254 (DSD-442 4.2 Liter), 362 (DSD-659 5.9 Liter) REMOTE SPIN ON LUBE	<b>18-7875</b>
3.7L, 5.2L Replaces: Chrysler 3549957 L-19, L-1008	<b>18-7819</b>	91—V4, 104 V4, 380 (DSD-662 6.2 Liter) SPIN ON LUBE	<b>18-7878</b>
<b>Commander</b> 225, 340 Clever SPIN ON LUBE	<b>18-7875</b>	<b>GM</b> 6-194 (1962-67), 6-230 (1963-68), V8-305 (1976-78), V8-307 (1970-73), V8-350 (1970-87), V8-366 (1970-87), V8-400 (1971-72, 1975-83), V8-454 (1973-87) SPIN ON LUBE	<b>18-7824</b> <b>18-7876</b>
<b>Crusader</b> 150, 160,165, CH185, 210, CH220, CH270, 350, CH350 SPIN ON LUBE Replaces: Crusader 201104	<b>18-7824</b>	V8-267 (1979-81), V8-305 (1979-87), V8-350(1978-81), V8-400 (1974-77) SPIN ON LUBE	<b>18-7824</b>
SS330 REMOTE MOUNT SPIN ON LUBE Replaces: Crusader 201104 Replaces: Crusader 201104	<b>18-7876</b> <b>18-7824</b> <b>18-7824</b>	<b>Greenwich</b> Porpoise (w/IH V8-275B) SPIN ON LUBE	<b>18-7875</b>
220 Conquerer,255 Conquerer, 255 Conquerer Jet, 250 (71), 300 Scorpion, 460 SPIN ON LUBE	<b>18-7875</b>	<b>Honda</b> BF25, BF30, A,AW,AX,AY Series# 14ZV90E1M, BF35/45M, BF40/50A,AW,AX, Series #14ZV50M Replaces: Honda 1500-PFB-004 BF75, BF90, AT,AW,AX,AY, Series # 14ZW00E1M, BF115, BF130, AX,AY,A1, Series # 14ZW50E1M 75 HP & up Replaces: Honda 15400-POH-305PE, 15400-POH-305 SPIN ON LUBE	<b>18-7911</b> <b>18-7910</b>
220, 300, 320,325 REMOTE MOUNT SPIN ON LUBE	<b>18-7878</b>	<b>Hydro-Marine</b> All Models (Knecht FO335/1) SPIN ON LUBE	<b>18-7875</b>
<b>Cummins</b> V-555, VT-555, N-855, NT-855, NTA-855, V-903, VT-903, VTA-903, KT-1150, KTA-1150, VT-1710, VTA-1710, KT-2300, KTA-2300, KTA-3067 Replaces: Cummings 299670	<b>18-7874</b>	<b>Indmar</b> 250 SPIN ON LUBE	<b>18-7875</b>
<b>Daytona</b> 200, 292, 300, 350,400, 427,427A,427B SPIN ON LUBE	<b>18-7824</b> <b>18-7876</b> <b>18-7824</b>	275 (SP), 300 (SP) , 350-2, 350-4, 350(SP), 454-2, 454-4, 400 (SP) SPIN ON LUBE	<b>18-7876</b> <b>18-7824</b>
<b>Detroit Diesel</b> 2-71 (142), 3-71 (213), 4-53 (212), 4-71 (284), 6V-53 (318), 6-71 (426), 6-71E (426), 671N (426), 6-71T (426), 6V-71 (426), 6V-71T (426), 6V-92 (552), 6V-92T (522), 8V-71 (568), 8V-71T (568), 8V-92 (736), 8V-92T (736), 12V-71 (1788), 12V-71T (1788),			